



**SITE INSPECTION REPORT**  
 New Hampshire Department of Environmental Services  
 Drinking Water and Groundwater Bureau  
 29 Hazen Drive; PO Box 95  
 Concord, NH 03302-0095



System Name: Danville Elementary School PWS ID: 0585010  
 Town Danville Site Visit #: 22001 Sanitary  
 Survey Date: 8/30/22

Pursuant to RSA 485 and NH Administrative Rules Env-Dw 717 and 720, a site inspection or consultation was conducted on the above public water system by DWGB staff. Significant deficiencies which have a direct impact on the water system's water quality or reliability are cited below. All significant deficiencies must be corrected by **30 days** (or sooner if so noted), **OR** a Corrective Action Plan (CAP) that outlines the proposed corrective actions and schedule must be submitted by **30 days** from receipt of this report. Failure to comply with these requirements or to comply with a DES-approved CAP will result in an enforcement action by NHDES.

**Significant Deficiencies**

- |  |  |
|--|--|
| <input type="checkbox"/> Well is Not Sealed (SAN)                    | <input type="checkbox"/> Unsanitary Pump House (UNP)                       |
| <input type="checkbox"/> Well Damaged/Subject to Contamination (WSC) | <input type="checkbox"/> Treatment Inoperative (TRF)                       |
| <input type="checkbox"/> Well Construction Inadequate (WCI)          | <input type="checkbox"/> Design Review Approval Required (DRA)             |
| <input type="checkbox"/> Well can be flooded (FLW)                   | <input type="checkbox"/> Backflow Prevention Device Required (BFP)         |
| <input type="checkbox"/> Buried Well (BUW)                           | <input type="checkbox"/> Storage Tank subject to Contamination (STO)       |
| <input type="checkbox"/> Contaminants in Well Radius (HWR)           | <input type="checkbox"/> Storage Tank Maintenance Required (STM)           |
| <input type="checkbox"/> Sampling Tap Required (TAP)                 | <input type="checkbox"/> No Atmospheric Storage Tank Fill Pipe – CWS (AFP) |
| <input type="checkbox"/> Source Meters Lacking (MET)                 | <input type="checkbox"/> Operation & Maintenance Inadequate (OAM)          |

Other Significant Deficiencies: BUS business plan required; CSH confined space hazard; DUP 2<sup>nd</sup> booster pump needed; FPH pump house can flood; HPH hazardous materials in/around pump house; LPC low or neg. pressure; **NAW unauthorized well online**; RDG needs record drawings; RPT inadequate records or reporting; SCV source capacity; SEC security / vandalism; VLT well in undrained vault; WPI well pump inoperative; ZAP electrical hazard.

Other Significant Deficiencies / Comments:

**No Significant System Deficiencies Noted**

**SPA – well is located adjacent to the ball field and playground, 100' south of the school**

**CORRECT AND NOTIFY DES IN WRITING AND/OR SUBMIT CORRECTIVE ACTION PLAN**

This Site Inspection Report summarizes requirements for correction and written notification to DES, or submittal of a written Corrective Action Plan for any significant deficiencies identified during the referenced REMOTE Sanitary Survey. I understand the is due **within 30 days of receipt of this report**.

Daniel Wojcik, Primary Operator  
 Owner / Owner's Representative / Certified Operator (Select One)

9/6/22 via e-mail  
 Date Sent to Owner

Mary Clairmont, DES  
 DWGB Surveyor Signature

8/30/22  
 Date